## 1001299: B40002 Crisis and Recovery Center

## **Proposal Request Log**

Last Updated: 11/04/24

| PR#          | Issued Date          | Description  | Amount        | Final<br>Action   | Final Action<br>Date | Notes/Explanation  |
|--------------|----------------------|--|---------------|-------------------|----------------------|--|
| PR 1         | 09/07/23             | Numerous items   | \$76,058.94   | Accepted          | 01/18/24             | Site/Civil changes to meet SPRWS requirements; civil coordination.   |
| 1.0          | 09/07/23             | Civil changes per BMI narrative and drawing changes  | \$52,821.71   | Accepted          | 01/18/24             |  |
| 1.1          | 09/07/23             | Wood door finish clarifications  | \$0.00        | Accepted          | 01/18/24             |  |
| 1.2          | 09/07/23             | Glazing thickness changes  | \$0.00        | Accepted          | 01/18/24             |  |
| 1.3          | 09/07/23             | Roof membrane change from 90-mil to 60-mil   |               |                   |                      |  |
| 1.4          | 09/07/23             | Roof protection board changes on back side of parapets   | \$1,291.30    | Accepted          | 01/18/24             |  |
| 1.11         | 09/07/23             | Roof membrane warranty change from 30-year to 25-year  |               |                   |                      |  |
| 1.5          | 09/07/23             | Fire service line changes, relocate MAU-1  | \$0.00        | Accepted          | 01/18/24             |  |
| 1.6          | 09/07/23             | Separate domestic water and fire service; adjust sanitary location   | \$20,893.20   | Accepted          | 01/18/24             | Required changes from SPRWS; final resolution happened after bids, on 08/11/23.  |
| 1.7          | 09/07/23             | Revise cold water pipe sizes   |               |                   |                      | ,,,  |
| 1.8          | 09/07/23             | Electrical site scope changes  | \$0.00        | no change         | 12/21/23             |  |
| 1.10         | 09/07/23             | Update MSB schedule for EV charger   |               |                   |                      |  |
| 1.9          | 09/07/23             | Revise CC light fixture locations  | \$0.00        |                   | 01/18/24             |  |
| 1.12         | 09/07/23             | Omit sheet metal roofing materials  Revise door hardware set 06A   | \$1,052.73    | Accepted Accepted | 01/18/24             |  |
|              |                      |  |               | •                 |                      |  |
| 1.14         | 09/07/23             | Revise ACT-2 products  | \$0.00        |                   | 01/18/24             |  |
| 1.15<br>PR 2 | 09/07/23<br>11/27/23 | Omit cementitious siding paint system  Numerous items  | (\$31,530.96) | Accepted Accepted | 01/18/24<br>01/16/24 | Changes due to WSP P&Z reqs, owner furniture, B3 acoustic reqs, FM Global reqs, contractor proposed brick cost savings |
| 1.0          | 11/27/23             | Site Plan changes - resulting from WSP Planning &  | (\$33,714.25) | Accepted          | 01/16/24             | contractor proposed brick cost savings   |
| 1.0          | 11/27/23             | Zoning review comments Site Plan changes - resulting from WSP Planning &   | \$38,926.06   |                   | 01/16/24             |  |
|              |                      | Zoning review comments Plan changes: Mother's Room (wall   |               | Accepted          | 01/16/24             |  |
| 1.1          | 11/27/23             | locations/dimensions & counter depth), Training Kitchen (cabinet changes)  |               |                   |                      |  |
| 1.2          | 11/27/23             | Mech 1 B131 wall type changes to meet B3 STC ratings   |               |                   |                      |  |
| 1.3          | 11/27/23             | Mech 2 B207A wall type changes to meet B3 STC rating   | \$9,296.96    | Accepted          | Accepted 01/16/24    |  |
| 1.7          | 11/27/23             | Changed interior wall type GA3 to meet B3 STC ratings  |               |                   |                      |  |
| 1.8          | 11/27/23             | Clarified interior column fur outs, changed fur out in Mother's Room   | <u> </u>      |                   | 04 /4 5 /2 4         |  |
| 1.4          | 11/27/23             | Omit one type of corner guard  | \$0.00        | Accepted          | 01/16/24             |  |
| 1.5          | 11/27/23             | Change to stairwell handrails to Intastop  | \$0.00        | no change         | 12/20/23             |  |
| 1.6          | 11/27/23             | Curtainwall changes to remove narrow side panels, center assembly in recess, increase door width, change door hardware | (\$1,837.00)  | Accepted          | 01/16/24             |  |
| 1.9          | 11/27/23             | Change exterior wall assembly insulation to mineral wool; add vapor barrier  | \$0.00        | no change         | 12/21/23             |  |
| 1.10         | 11/27/23             | Change brick size to 4x4x16  | (\$45,000.00) | Accepted          | 01/16/24             |  |
| 1.11         | 11/27/23             | Reduced number of B1 light fixtures in Storage   |               | Accepted          | 01/16/24             |  |
| 1.11         | 11/2//23             | A115   |               | Accepted          | 01/10/24             |  |
| 1.12         | 11/27/23             | "No cost" Electrical plan sheets included to show<br>new device locations resulting from plan changes                  | (\$198.55)    | Accepted          | 01/16/24             |  |
| 1.13         | 11/27/23             | Revise sinks in Training Kitchen and Mother's Room   | \$492.20      | Accepted          | 01/16/24             |  |
| GC PR #1     | 12/13/23             | Eliminate static load testing of CMCs  | (\$15,000.00) | Accepted          | 12/27/23             | Stemmed from RFI 12; contractor proposed change through their means methods.   |
| GC PR#2      | 12/13/23             | Provide add'l lineal footage of CMC rigid inclusion piers to meet bearing elevations.                                  | \$22,273.20   | Accepted          | 12/19/23             | Contractor provided CMC installation log<br>showing average depth of 35.1' vs. intended<br>design of 31' depth.        |
| PR 3         | 12/20/23             | Site/Civil changes per WSP P&Z review letter   | \$1,771.00    | Accepted          | 01/16/24             | Site/Civil changes to meet WSP P&Z requirements.   |

| PR#            | Issued Date | Description  | Amount       | Final<br>Action | Final Action<br>Date | Notes/Explanation                                       |
|----------------|-------------|--|--------------|-----------------|----------------------|---|
| GC PR #3       | 01/09/24    | Elevator pit waterproofing   | \$5,382.00   | Accepted        | 01/16/24             | Contractor suggested changes to reduce risk.            |
| CO #1          | 01/18/24    | Change Order #1  | \$58,954.18  |                 | 02/01/24             |   |
| PR 4           | 01/19/24    | UGS redesign   | \$0.00       | Void            | 03/22/24             |   |
| GC PR #4<br>R1 | 03/14/24    | Contaminated soils remediation (excavation, hauling and disposal)  | \$131,731.15 | Accepted        | 06/25/24             | Add 15 working days                                     |
| GC PR #4B      | 03/28/24    | Contaminated soils remediation - over-excavation   | \$81,750.88  | Reject          | 03/28/24             |   |
| GC PR #5       | 03/13/24    | Site logistics costs related to discovery of contaminated soils (start/stop of UGS work, test pits, etc.)  | \$9,043.49   | Accepted        | 06/25/24             |   |
| CO #2          |             | Change Order #2  | \$140,774.64 |                 |                      |   |
| GC PR #6       | 03/18/24    | Change from standard handrail to anti-ligature handrail on back wall only in Elevator cab  | \$2,855.85   | Accepted        | 03/19/24             |   |
| PR 6           | 04/24/24    | Site Plan change to route sidewalk around existing power pole.   | \$1,529.50   | Accepted        | 06/27/24             |   |
| PR 7           | 05/10/24    | Changes resulting from substituted rear access MTS.  | \$0.00       | Void            | 06/28/24             |   |
| PR 8           | 05/23/24    | Interior Finish Changes  | \$0.00       |                 |                      |   |
| 8.0            | 05/23/24    | Change threshholds at (16) bedrooms from RTS1 (Schluter metal edge) to RTS2 (solid surface).   | \$13,714.22  | Reject          | 06/06/24             |   |
| 8.1            | 05/23/24    | Change threshholds at (2) ADA bedrooms only from RTS1 (Schluter metal edge) to RTS2 (solid surface).   | \$1,714.28   | Reject          | 06/06/24             |   |
| 8.2            | 05/23/24    | Provide Schluter metal edge strip SCH 5 at (2) threshholds to Comm Kitchen.  | \$0.00       | Accepted        | 06/06/24             |   |
| 8.3            | 05/23/24    | Removed LVT2 "plank direction" in (16) bedrooms per submittal review.  | \$0.00       | Accepted        | 06/06/24             |   |
| GC PR #7       | 05/29/24    | Sliding barn doors - custom frame color to match wall, change to anti-ligature hardware and sloped valence.  | \$13,386.08  | Reject          | 06/11/24             |   |
| GC PR #7<br>R1 | 06/11/24    | Sliding barn doors - change to anti-ligature<br>hardware; keep standard frame finish and<br>standard square valence.   | \$3,232.91   | Accepted        | 06/21/24             | Changes from submittal review.                          |
| GC PR #9       | 05/29/24    | SMC to purchase FD key box   | \$264.87     | Accepted        | 06/06/24             | County asked SMC to purchase and install on our behalf. |
| GC PR #10      | 05/29/24    | Increase size of exterior louver.  | \$237.90     | Accepted        | 06/06/24             | Stemming from RFI 35                                    |
| GC PR #11      | 05/29/24    | Framing for parapet height changes to be 42" high min.   | \$12,304.49  | Accepted        | 06/18/24             | Stemming from RFI 56                                    |
| GC PR #12      | 05/29/24    | Time and materials for elevator roof cap over-run.   | \$3,061.88   | Accepted        | 07/03/24             | Stemming from RFI 59                                    |
| GC PR #13      | 06/04/24    | Roof sheathing changes from 1/2" to 5/8" thick and add 1" insulation board per FM Global reqs.   | \$23,013.29  | Accepted        | 06/18/24             |   |
| PR 11          | 06/07/24    | Overflow roof drain drainage and downspout to storm sewer changes.   |              |                 |                      |   |
| 11.1           | 06/07/24    | Change concrete to mulch for storm overflow discharge on west side of building.  | \$75,440.81  | Accepted        | 06/18/24             |   |
| 11.2           | 06/07/24    | Connect downspouts from south wing sloped roof to storm sewer system.  |              |                 |                      |   |
| PR 12          | 06/13/24    | Fire Alarm System changes  |              |                 |                      |   |
| 12.1           | 06/13/24    | Change fire alarm panel from Onyx series to Insprie series (for CO detection capabilities)   | \$3,542.00   | Accepted        | 07/09/24             | Stemming from RFI 57                                    |
| 12.2           | 06/13/24    | Change bedroom devices to strobe-only, no horns.   |              |                 |                      |   |
| GC PR #14      | 06/18/24    | Add hat/furring channels at 16" oc.c. to truss<br>bottom chords to support drywall ceiling in Area<br>A.   | \$19,383.18  | Accepted        | 06/19/24             | Stemming from RFI 78                                    |
| GC PR #15      | 06/18/24    | Provide combo of drywall encasement and coating to protect firestopping and spray foam insulation used to create continuous vapor barrier at specific locations around building perimeter. | \$44,227.15  | Accepted        | 07/17/24             | Propose to add 10 working days                          |
| GC PR #16      | 06/24/24    | Change color of hardie board siding from Iron Gray to Last Embers.   | \$12,462.22  | Reject          | 07/03/24             |   |
| GC PR #17      | 06/25/24    | Aluminum window frame custom color in black.   | \$0.00       | Accepted        | 07/02/24             |   |

| PR#       | Issued Date | Description   | Amount        | Final<br>Action | Final Action<br>Date | Notes/Explanation  |
|-----------|-------------|---|---------------|-----------------|----------------------|--|
| GC PR #19 | 07/02/24    | Added duct insulation for revised duct routing through unconditioned space per RFI #75.   | \$9,080.40    | Accepted        | 07/12/24             |  |
| GC PR #20 | 07/03/24    | Additional metal coping material for raised parapet.  | \$6,440.00    | Accepted        | 07/08/24             | Stemming from RFI 56.  |
| PR 5      | 02/12/24    | Numerous items  | \$19,917.43   | Accepted        | 09/19/24             |  |
| 5.0       | 02/12/24    | Civil changes - EV charging station, updated grading and parking stall layout changes.  | \$0.00        | no change       | 06/18/24             |  |
| 5.1       | 02/12/24    | Deleted Hub casework  |               |                 |                      |  |
| 5.2 Rev 1 | 04/23/24    | Changed Dining Area ceiling from gyp board to 24x24 ACT with stylestix grid covers  | _             |                 |                      |  |
| 5.3       | 02/12/24    | Added WT3 in (2) Retreat Rooms; interior finish changes; vinyl graphic spec info  | \$6,538.60    | Accepted        | 08/07/24             |  |
| 5.8       | 02/12/24    | Fire protection changes in Dining Room due to change in ceiling type  |               |                 |                      |  |
| 5.4       | 02/12/24    | Change stairway handrails to wood custom profile  | \$12,172.00   | Accepted        | 09/19/24             |  |
| 5.5       | 02/12/24    | Change exterior wall insulation from spray foam to 6" thick fiber glass batt fill; add vapor barrier; update window sill brick rowlock details                                | (\$18,435.00) | Accepted        | 04/26/24             |  |
| 5.6       | 02/12/24    | Mechanical changes: various plumbing piping and vent changes from RFI 13; commercial kitchen plumbing changes from food service equip submittal                               | \$15,038.55   | Accepted        | 04/16/24             |  |
| 5.7       | 02/12/24    | Mechanical changes: revise VRF refrigerant piping and DOAS-1 selection  |               |                 |                      |  |
| 5.9       | 02/12/24    | Electrical changes: EV charging stations; various interior lighting, switch and receptacle changes; REX and detector changes.   | \$4,603.28    | Accepted        | 06/18/24             |  |
| 5.10      | 02/12/24    | Electrical changes: revise motor details and breaker sizes/types.   |               |                 |                      |  |
| PR 9 R1   | 06/19/24    | Electrical changes, add heat tape   |               |                 |                      |  |
| 9.1       | 06/19/24    | Revise receptacle heights and locations for washers and dryers to be at 46" a.f.f.; add (2) receptacles; change 1 receptacle to a non-GFCI, provide remote GFCI test station. |               |                 |                      |  |
| 9.2       | 06/05/24    | Provide heat tape and necessary electrical connections.   | 62F 264 7F    | Accomtod        | 09/20/24             |  |
| 9.3       | 06/05/24    | Revise light schedule for new selection for "Z" fixture.  | \$35,264.75   | Accepted        | 08/29/24             |  |
| 9.4       | 06/05/24    | Provide 30mA Ground Fault Equip Protection breakers for heat tape circuits.   |               |                 |                      |  |
| 9.5       | 06/19/24    | Provide a 30A/2P GFCI breaker for (2) added dryer receptacles.  |               | <u> </u>        |                      |  |
| PR 10     | 06/05/24    | Door hardware changes   |               |                 |                      |  |
| 10.1      | 06/05/24    | Add card access readers, door hardware changes and component changes/additions at A125 and A130.  | \$16,003.41   | Accepted        | 08/07/24             |  |
| 10.2      | 06/05/24    | Door Schedule changes to add card readers and change door hardware components.  | Ţ_5)005.41    |                 | /-/-                 |  |
| 10.3      | 06/05/24    | Change (14) doors to use Primus cylinders.  |               |                 |                      |  |
| GC PR #18 | 06/26/24    | Added contractor time to research options for MTS; added time for MTS lead time.  | \$9,027.50    | Reject          | 10/09/24             |  |
| PR 13     | 07/22/24    | Add vinyl graphic and metal trim to wall across from PA station.  | \$2,009.17    | Accepted        | 08/21/24             |  |
| PR 14     | 07/29/24    | Add sidewall sprinklers and extension of sprinkler system to east covered porch to meet fire protection requirements.   | \$3,030.25    | Accepted        | 08/07/24             | Fire protection or non-combustible materials req'd per code. |
| GC PR #21 | 07/31/24    | Add sheet metal "fire break" between polyiso and mineral wool insulations.  | \$7,186.35    | Accepted        | 08/29/24             | Stemming from RFI 91.  |
| GC PR #22 | 08/13/24    | Upgrade thermally modified wood from Southern<br>Yellow Pine to Ash; includes UV protectant coating.  | \$50,851.85   | Reject          | 08/14/24             |  |

| PR#       | Issued Date | Description  | Amount      | Final<br>Action | Final Action<br>Date | Notes/Explanation      |
|-----------|-------------|--|-------------|-----------------|----------------------|------------------------|
| GC PR #23 | 08/13/24    | Add (1) coat of UV protectant to the thermally modified wood (Southern Yellow Pine species).   | \$17,789.35 | Reject          | 08/20/24             |                        |
| PR 18     | 08/15/24    | Irrigation system clarifications. revise location of<br>water supply connection in building; add irrigation<br>lines with deduct meter and associaetd<br>components.   | \$7,004.65  | Accepted        | 09/06/24             | Stemming from RFI 93.  |
| PR 16     | 08/16/24    | CUH Relocation/Clarificaitons.<br>swap CUH-3 and CUH-6; move CUH-5 to north<br>wall; adjust CUH-6 and light fixture in Vest A129;<br>relocate elect connections CUH-5 and CUH-6;<br>provide CUH-6 with ceiling conversion kit. | \$293.25    | Accepted        | 09/06/24             | Stemming from RFI 92.  |
| GC PR #24 | 09/06/24    | Change duplex to quad outlet in (16) bedrooms to meet Elect Inspector's reqs; patch/paint walls at (8) rooms.  | \$4,965.21  | Accepted        | 09/30/24             | Stemming from RFI 98.  |
| PR 19     | 09/10/24    | Change light fixture at East Porch to be 7" surface mounted puck light with black trim finish.   | \$1,748.00  | Accepted        | 09/23/24             | Stemming from RFI 102. |
| GC PR #26 | 09/18/24    | Add'l excavation time and labor at monument sign, to work around existing fiber lines.   | \$672.98    | Accepted        | 09/23/24             | Stemming from RFI 97.  |
| GC PR #27 | 09/18/24    | Parking lot light and pole changes.  | \$1,754.44  | Accepted        | 09/23/24             | Stemming from RFI 99.  |
| GC PR #28 | 09/18/24    | Changes to light cove and soffit details in Retreat<br>Rooms 104 and 105 and Wellness Room 145.  | \$3,204.60  | Accepted        | 09/23/24             | Stemming from RFI 101. |
| GC PR #29 | 10/02/24    | Adjust wall tile layout in (21) RRs to add wall tile base and cut wall tile.   | \$6,706.23  | Accepted        | 10/16/24             |                        |
| GC PR #30 | 10/03/24    | Hardware changes at serving window sliding doors.  | \$4,941.48  | Accepted        | 10/11/24             |                        |
| GC PR #31 | 10/08/24    | Change color of metal window sills from black to gra to match adjacent material color.   | \$4,629.90  | Reject          | 10/10/24             |                        |
| PR 21     | 10/14/24    | Add surface mounted outlet to Pavilion column; feed circuit from CC light fixtures.  | \$2,210.30  | Accepted        | 10/23/24             |                        |
| GC PR #34 | 10/18/24    | Provide thermally modified wood material on all members at south and north trellis.  | \$41,316.05 | Accepted        | 10/23/24             |                        |
| GC PR #35 | 10/29/24    | Add'l stud framing at electrical panels in commercial kitchen.   | \$1,100.77  | Accepted        | 10/31/24             | Stemming from RFI 94.  |

Total of Approved Changes to Date: \$199,728.82

Total of Proposed Changes: \$363,943.55 Add 10 working days

Total of all Changes: \$563,672.37